US Department of Energy Groundwater Database Groundwater Master Report

Installation Name, State: Ashtabula

Responsible DOE Office: Office of Environmental Management

Plume Name: Ashtabula

Remediation Contractor: Unknown
Report Last Updated: Unknown

Contaminants

Halogenated VOCs/SVOCs Present? Yes

VOC Name	Concentration (ppb)	Regulatory Driver	Cleanup Requirement
TCE	440000	No	
VC	47	No	

Fuel Present? **No**Metals Present? **Yes**

Metal Name	Metal Concentration (ppb)	Regulatory Driver	Cleanup Requirement
Pb	28	No	
Ва	3222	No	

Isotopes Present? Yes

Isotope Name	Isotope Activity (pCi/l)	Regulatory Driver	Cleanup Requirement
Тс	591000	No	
U	12400	No	

Explosives Present? **Yes**Other Contaminants?**No**Tritium Present? **No**

Nitrates Present? **Yes**Concentration: **5750000** (ppb)

Sulfates Present? **Yes**Concentration: **470000** (ppb)

Hydrogeology

Conduit Flow? **Yes** Depth (feet): **30**

Multiple Units Affected? **No**Avg Velocity (feet/year): **3.9**

Plume Information (no source)

Source **Active** Area of Plume (acres): **54450**

Plume Status No Response

Remedial Approach

Remedy Name	Status	Start Date	End Date
bioremediation	Confirmed	2002	2005
excavate	Confirmed	2003	2006
pump and treat	Confirmed		2018

Groundwater Use / Exit Strategy

Potable? **No**Does an Exit Strategy Exist? **Yes**

Sole Source Aquifer? No Basis for Exit Strategy: Target Concentration

Environmental Indicators (EIs)

Groundwater Migration Under Control? **No**Confirmed by Lead Regulator? **No**Current Human Exposure Acceptable? **No**Confirmed by Lead Regulator? **No**

Regulatory

Decision Document? **Remedial Approach Proposed**Date Approved

Regulatory Position on Groundwater Use Same as Site?

Comments

References: 1) RFI Equivalency Document, RMI Extrusion Plant (Eckenfelder, Inc., 1989) 2) Phase I Ground Water Investigation at the RMI Extrusion Plant Site (Sharp and Associates, Inc., 2002) 3) Bioremdiation of TCE-Contaminated Soil, Quarter 1 Sampling Report (Satety and Ecology Cooperation, 2002)